2007 ACCESSORIES & BODY, CAB Symptom Troubleshooting (Instrument Cluster) - MX-5 Miata

2007 ACCESSORIES & BODY, CAB

Symptom Troubleshooting (Instrument Cluster) - MX-5 Miata

SYMPTOM TROUBLESHOOTING [INSTRUMENT CLUSTER]

SYMPTOM TROUBLESHOOTING TABLE

No.	TROUBLESHOOTING ITEM	REFERENCE
1	Fuel gauge needle position incorrect	(See NO.1 FUEL GAUGE NEEDLE POSITION INCORRECT.)
2	All meters and gauges do not operate	(See NO.2 ALL METERS AND GAUGES DO NOT OPERATE .)
3	ABS warning light illuminates	(See NO.3 ABS WARNING LIGHT ILLUMINATES .)
4	MIL illuminates	(See NO.4 MIL ILLUMINATES .)
5	Brake system warning light illuminates	(See NO.5 BRAKE SYSTEM WARNING LIGHT ILLUMINATES .)
6	Instrument cluster illumination does not illuminate	(See NO.6 INSTRUMENT CLUSTER ILLUMINATION DOES NOT ILLUMINATE.)
7	Speedometer indication is defective	(See NO.7 SPEEDOMETER INDICATION IS DEFECTIVE .)
8	Tachometer indication is defective	(See NO.8 TACHOMETER INDICATION IS DEFECTIVE .)
9	Water temperature gauge indication is defective	(See NO.9 WATER TEMPERATURE GAUGE INDICATION IS DEFECTIVE .)
10	Oil pressure gauge indication is defective (oil pressure gauge needle does not move from the L position or less)	(See NO.10 OIL PRESSURE GAUGE INDICATION IS DEFECTIVE (OIL PRESSURE GAUGE NEEDLE DOES NOT MOVE FROM THE L POSITION OR LESS) .)

QUICK DIAGNOSTIC TABLE [INSTRUMENT CLUSTER]

2007 ACCESSORIES & BODY, CAB Symptom Troubleshooting (Instrument Cluster) - MX-5 Miata

		_		_	_	_	_	_	_	_			_	_	_	_	_	_	_	_	X:	: Ar	pli	cal	ole
No.	Possible factor Troubleshooting item	Poor connection of fuel gauge sender unit connector, terminal damage	Poor connection of instrument cluster connector, terminal damage	Fuel gauge sender unit	Instrument cluster	Fuel gauge sender unit is improperly installed	Open or short circuit in wiring harness between instrument cluster and GND	Open or short circuit in wiring harness between instrument cluster and fuel gauge sender unit	Fuse malfunction (METER)	Open or short circuit in power supply (IG1) wiring harness	Open or short circuit in GND wiring harness ABS HU/CM or DSC HU/CM	Poor connection of ABS HU/CM or DSC HU/CM connector, terminal damage	ABS HU/CM or DSC HU/CM	Short circuit in wiring harness between CAN-L, CAN-H and GND	Open circuit in CAN wiring harness (CAN-L, CAN-H)	CAN wiring harness (CAN-L, CAN-H) short each other	Poor connection of PCM connector, terminal damage	PCM	Poor connection of brake fluid level sensor connector, terminal damage	Brake fluid level sensor	Poor connection of Parking brake switch connector, terminal damage	Parking brake switch	Fuse malfunction (ROOM, ILLUMI)	Poor connection of oil pressure switch connector, terminal damage	Oil pressure switch
1	Fuel gauge needle position incorrect	Х	Х	X	X	X	х	х																	L
2	All meters and gauges do not operate		X		Х			_	Х	х	Х				_				L.						
3	ABS warning light illuminates	Ц	X	_	Х				_			X	Х	Х	X	Х		_							
4	MIL illuminates	L	Х		Х	L	L							Х	X	Х	X	X							_
5	Brake system warning light illuminates	Ш	Х		х							х	X	х	Х	x			х	х	х	х			
6	Instrument cluster illumination does not illuminate	Ш	X		х																		х		
7	Speedometer indication is defective		х		х							х	х	х	х	х	х	х							
8	Tachometer indication is defective		Х		х									х	х	х	х	Х							
9	Water temperature gauge indication is defective		Х		х									х	х	х	х	х							
10	Oil pressure gauge indication is defective (oil pressure gauge needle does not move from the L position or less)		x		x									х	x	х	x	х						x	x

Fig. 1: Instrument Cluster Quick Diagnostic Table Courtesy of MAZDA MOTORS CORP.

NO. 1 FUEL GAUGE NEEDLE POSITION INCORRECT

FUEL GAUGE NEEDLE POSITION INCORRECT POSSIBLE CAUSE TABLE

1	Fuel gauge needle position incorrect
	Fuel gauge sender unit malfunctionInstrument cluster malfunction
	Connector or pin malfunction

2007 ACCESSORIES & BODY, CAB Symptom Troubleshooting (Instrument Cluster) - MX-5 Miata

POSSIBLE CAUSE

- Fuel gauge sender unit is improperly installed
- Open or short circuit in wiring harness between instrument cluster and GND
- Open or short circuit in wiring harness between instrument cluster and fuel gauge sender unit

DIAGNOSTIC PROCEDURE

STEP	INSPECTION		ACTION
1	 Turn the ignition switch to the ON position. Verify that the fuel gauge needle does not move 	Yes	Troubleshooting completed.
1	after ignition switch is turned off, or the display does not indicate F even though fuel tank is full.Is the fuel gauge normal?	No	Go to the next step.
•	 Start the instrument cluster input/output check mode. 	Yes	Go to the next step.
2	Select the check code 22.Display value is 7-206?	No	Go to Step 4.
2	Perform the check code 23 inspection.	Yes	Replace the instrument cluster.
3	• Is there any malfunction?	No	Go to the next step.
4	Perform the check code 22 inspection.	Yes	Go to the next step.
4	• Is there any malfunction?	No	Go to Step 6.
5	 Turn the ignition switch off. Inspect the instrument cluster connector terminals for poor connection (such as damaged/pulled-out pins, and corrosion). Are the terminals normal? 	Yes	Replace the instrument cluster.
3	2W 2U 2S 2Q 2O 2M 2K 21 2G 2E 2C 2A 2X 2V 2T 2R 2P 2N 2L 2J 2H 2F 2D 2B	No	Repair or replace the terminal.
6	 Turn the ignition switch to LOCK position. Remove the instrument cluster. Disconnect the instrument cluster connector. Inspect for continuity between the following wiring harnesses. 		Repair or replace the wiring harness between the instrument cluster and GND.

2007 ACCESSORIES & BODY, CAB Symptom Troubleshooting (Instrument Cluster) - MX-5 Miata

	 2R terminal-GND 2T terminal-GND Is there continuity? 	No	Go to the next step.
7	 Turn the ignition switch off. Inspect the fuel gauge sender unit connector 	Yes	Go to the next step.
,	terminals for poor connection (such as damaged/pulled-out pins, and corrosion).Are the terminals normal?		Repair or replace the terminal.
	• Turn the ignition switch to LOCK position.	Yes	Go to the next step.
8	 Inspect for continuity following the wiring harness between instrument cluster and fuel gauge sender unit. 2R terminal-C terminal 2T terminal-A terminal Is there continuity? 	No	Repair or replace the wiring harness between the instrument cluster and the fuel gauge sender unit.
9	Turn the ignition switch off.	Yes	Inspect the fuel gauge sender unit.
	 Is the fuel gauge sender unit installed properly? 	No	Reinstall the fuel gauge sender unit.

NO. 2 ALL METERS AND GAUGES DO NOT OPERATE

ALL METERS AND GAUGES DO NOT OPERATE POSSIBLE CAUSE TABLE

2 All meters and gauges do not operate			
	Instrument cluster malfunctionConnector or pin malfunction		
POSSIBLE CAUSE	Fuse malfunction		
	Open or short circuit in power supply (IG1) wiring harness		
	Open or short circuit in GND wiring harness		

DIAGNOSTIC PROCEDURE

STEP	INSPECTION		ACTION
1	 Turn the ignition switch to the ON position. Inspect the following: Does the odometer/tripmeter 	Yes	Troubleshooting completed.
1	 illuminate? Does the fuel gauge operate? Does the MIL turn off within approx. 3 s? 		Go to the next step.

2007 ACCESSORIES & BODY, CAB Symptom Troubleshooting (Instrument Cluster) - MX-5 Miata

		Yes	Go to the next step.
2	Inspect the METER fuse.Is the fuse normal?	No	Replace the fuse. • If the fuse is melted, inspect the wiring harness for a short to ground. Repair or replace the wiring harness, then replace the fuse.
	 Turn the ignition switch to LOCK position. Remove the instrument cluster. Disconnect the instrument cluster connector. Inspect the voltage between instrument cluster wiring harness-side connector terminal 1G and terminal 1E. 	Yes	Go to the next step.
3	Turn the ignition switch to the ON position. Is the voltage B+? IK 11 1G 1E 1C 1A IL 1J 1H 1F 1D 1B	No	Inspect the suspect wiring harness, then repair or replace.
4	 Turn the ignition switch off. Inspect the instrument cluster connector terminals for poor connection (such as 	Yes	Replace the instrument cluster.
7	terminals for poor connection (such as damaged/pulled-out pins, and corrosion). • Are the terminals normal?		Repair or replace the terminal.

NO. 3 ABS WARNING LIGHT ILLUMINATES

ABS WARNING LIGHT ILLUMINATES POSSIBLE CAUSE TABLE

3	ABS warning light illuminates
POSSIBLE CAUSE	 ABS HU/CM or DSC HU/CM malfunction Instrument cluster malfunction Connector or pin malfunction Short circuit in wiring harness between CAN-L, CAN-H and GND Open circuit in CAN wiring harness (CAN-L, CAN-H)

2007 ACCESSORIES & BODY, CAB Symptom Troubleshooting (Instrument Cluster) - MX-5 Miata

• CAN wiring harness (CAN-L, CAN-H) short each other

DIAGNOSTIC PROCEDURE

STEP	INSPECTION	ACTION	
1	Start the engine.	Yes	Troubleshooting completed.
1	• Does the ABS warning light turn off?	No	Go to the next step.
2	Are there a number of warning lights		Go to Step 4.
	illuminated?	No	Go to the next step.
3	 Start the instrument cluster input/output check mode. 	Yes	Inspect the ABS HU/CM or DSC HU/CM.
	 Does the ABS warning light turn off with a check code other than 26? 	No	Replace the instrument cluster.
4	 Disconnect the negative battery cable. Measure the resistance between the DLC-2 	Yes	Go to the next step.
4	terminals F and E. • Is the resistance 54-66 ohms ?		Go to Step 6.
5	 Inspect the DLC-2 terminals F and E for short to power supply or GND. Is there any malfunction? 		Inspect the wiring harness and CAN system-related module. Repair or replace the malfunctioning part.
			Replace the instrument cluster.
	 Turn the ignition switch off. Inspect the instrument cluster connector terminals for poor connection (such as damaged/pulled-out pins, and corrosion). Are the terminals normal? 	Yes	s Go to the next step.
6	1K 1I 1G 1E 1C 1A 1L 1J 1H 1F 1D 1B	No	Repair or replace the terminal.
7	 Disconnect the negative battery cable. Measure the resistance between the instrument 	Yes	Inspect the wiring harness and CAN system-related module. Repair or replace the malfunctioning part.
	cluster connector terminals 1J and 1L.	No	Replace the instrument cluster.

2007 ACCESSORIES & BODY, CAB Symptom Troubleshooting (Instrument Cluster) - MX-5 Miata

• Is the resistance 114-126 ohms ?		
---	--	--

NO. 4 MIL ILLUMINATES

MIL ILLUMINATES POSSIBLE CAUSE TABLE

4	MIL illuminates
	PCM malfunctionInstrument cluster malfunction
POSSIBLE CAUSE	Connector or pin malfunction
	Short circuit in wiring harness between CAN-L, CAN-H and GND
	Open circuit in CAN wiring harness (CAN-L, CAN-H)
	 CAN wiring harness (CAN-L, CAN-H) short each other

DIAGNOSTIC PROCEDURE

STEP	INSPECTION	ACTION		
1	Start the engine.	Yes	Troubleshooting completed.	
1	• Does the MIL turn off?	No	Go to the next step.	
2	Are there a number of warning lights	Yes	Go to Step 4.	
	illuminated?	No	Go to the next step.	
3	 Start the instrument cluster input/output check mode. 	Yes	Inspect the PCM.	
<i>J</i>	• Does the MIL turn off with a check code other than 26?	No	Replace the instrument cluster.	
	Measure the resistance between the DLC-2 terminals F and F.	Yes	Go to the next step.	
4			-	
		No	Go to Step 6.	
	• Is the resistance 34-00 onnis ?		Inspect the wiring harness and CAN	
_	to power supply or GND.	Yes	system-related module. Repair or	
5			replace the malfunctioning part.	
	• Is there any malfunction?	No	Replace the instrument cluster.	
	 Turn the ignition switch off. Inspect the instrument cluster connector terminals for poor connection (such as damaged/pulled-out pins, and corrosion). Are the terminals normal? 	Yes	Go to the next step.	

2007 ACCESSORIES & BODY, CAB Symptom Troubleshooting (Instrument Cluster) - MX-5 Miata

6	1K 1I 1G 1E 1C 1A 1L 1J 1H 1F 1D 1B	No	Repair or replace the terminal.
7	 Disconnect the negative battery cable. Measure the resistance between the instrument cluster connector terminals 1J and 1L. 	Yes	Inspect the wiring harness and CAN system-related module. Repair or replace the malfunctioning part.
	• Is the resistance 114-126 ohms?	No	Replace the instrument cluster.

NO. 5 BRAKE SYSTEM WARNING LIGHT ILLUMINATES

BRAKE SYSTEM WARNING LIGHT ILLUMINATES POSSIBLE CAUSE TABLE

5	Brake system warning light illuminates
	ABS HU/CM or DSC HU/CM malfunction
	Brake fluid level sensor malfunction
	Parking brake switch malfunction
POSSIBLE CAUSE	Instrument cluster malfunction
1 OSSIDLE CAUSE	Connector or pin malfunction
	 Short circuit in wiring harness between CAN-L, CAN-H and GND
	 Open circuit in CAN wiring harness (CAN-L, CAN-H)
	 CAN wiring harness (CAN-L, CAN-H) short each other

DIAGNOSTIC PROCEDURE

STEP	INSPECTION		ACTION
	• Start the engine.	Yes	Troubleshooting completed.
1	Release the parking brake.		
	• Does the brake system warning light turn off?	No	Go to the next step.
2	• Are there a number of warning lights		Go to Step 5.
2	illuminated?	No	Go to the next step.
2		Yes	Add brake fluid.
3	• Does the brake fluid need replenishment?	No	Go to the next step.
	• Start the instrument cluster input/output check	Yes	Inspect the ABS HU/CM, DSC
	mode.		HU/CM, brake fluid level sensor

2007 ACCESSORIES & BODY, CAB Symptom Troubleshooting (Instrument Cluster) - MX-5 Miata

4	Does the brake system warning light turn off		parking brake switch or connectors.
	with a check code other than 26?	No	Replace the instrument cluster.
	 Disconnect the negative battery cable. Measure the resistance between the DLC-2 		Go to the next step.
5	terminals F and E	No	Go to Step 7.
6	 Disconnect the negative battery cable. Inspect the DLC-2 terminals F and E for short to power supply or GND. 		Inspect the wiring harness and CAN system-related module. Repair or replace the malfunctioning part.
	• Is there any malfunction?	No	Replace the instrument cluster.
	 Turn the ignition switch off. Inspect the instrument cluster connector terminals for poor connection (such as damaged/pulled-out pins, and corrosion). Are the terminals normal? 	Yes	Go to the next step.
7	1K 11 1G 1E 1C 1A 1L 1J 1H 1F 1D 1B	No	Repair or replace the terminal.
8	 Disconnect the negative battery cable. Measure the resistance between the instrument cluster connector terminals 1J and 1L. 		Inspect the wiring harness and CAN system-related module. Repair or replace the malfunctioning part.
	• Is the resistance 114-126 ohms ?	No	Replace the instrument cluster.

NO. 6 INSTRUMENT CLUSTER ILLUMINATION DOES NOT ILLUMINATE

INSTRUMENT CLUSTER ILLUMINATION DOES NOT ILLUMINATE POSSIBLE CAUSE TABLE

INSTRUMENT CLOSTER ILLUMINATION DOES NOT ILLUMINATE TOSSIBLE CAUSE TAI					
6	Instrument cluster illumination does not illuminate				
POSSIBLE CAUSE	 Instrument cluster malfunction Connector or pin malfunction 				
	Fuse malfunction				

2007 ACCESSORIES & BODY, CAB Symptom Troubleshooting (Instrument Cluster) - MX-5 Miata

DIAGNOSTIC PROCEDURE

STEP	INSPECTION		ACTION
1	• Turn the light switch to the TNS position.	Yes	Troubleshooting completed.
1	 Does the instrument cluster illumination turn on? 	No	Go to the next step.
2	• Does the non-illumination include the entire	Yes	Go to the next step.
	instrument cluster?	No	Replace the instrument cluster.
		Yes	Go to the next step.
			Replace the fuse.
3	Inspect the ROOM and ILLUMI fuse.Are the fuses normal?	No	If the fuse is melted, inspect the wiring harness for short to ground. Repair or replace the wiring harness, then replace the fuse.
4	 Turn the ignition switch off. Inspect the instrument cluster connector terminals for poor connection (such as damaged/pulled-out pins, and corrosion). Are the terminals normal? 	Yes	Replace the instrument cluster.
4	1K 1I 1G 1E 1C 1A 1L 1J 1H 1F 1D 1B	No	Repair or replace the terminal.

NO. 7 SPEEDOMETER INDICATION IS DEFECTIVE

SPEEDOMETER INDICATION IS DEFECTIVE POSSIBLE CAUSE TABLE

7 Speedometer indication is defective				
	ABS HU/CM or DSC HU/CM malfunction			
	PCM malfunction			
	Instrument cluster malfunction			
POSSIBLE CAUSE	Connector or pin malfunction			
	Short circuit in wiring harness between CAN-L, CAN-H and GND			
	Open circuit in CAN wiring harness (CAN-L, CAN-H)			
	CAN wiring harness (CAN-L, CAN-H) short each other			

2007 ACCESSORIES & BODY, CAB Symptom Troubleshooting (Instrument Cluster) - MX-5 Miata

DIAGNOSTIC PROCEDURE

STEP	INSPECTION		ACTION
1	 Start the engine, and drive the vehicle. Does the speedometer needle move smoothly? 	Yes	Troubleshooting completed.
	 Does the speedometer needle indicate correct speed? 	No	Go to the next step.
2	• Do the tachometer, the water temperature	Yes	Go to the next step.
2	gauge, and the oil pressure gauge operate normally?	No	Go to Step 4.
3	 Start the instrument cluster input/output check mode. Inspect the speedometer using the check code 	Yes	Inspect the ABS HU/CM, DSC HU/CM, or connectors.
	12.Is the speedometer normal?	No	Replace the instrument cluster.
4	• Start the engine.	Yes	Inspect the PCM or connectors.
4	Does the ABS warning light turn off?	No	Replace the instrument cluster.
5	 Disconnect the negative battery cable. Measure the resistance between the DLC-2 terminals F and E. Is the resistance 54-66 ohms? 	Yes	Go to the next step.
		No	Go to Step 7.
6	 Disconnect the negative battery cable. Inspect the DLC-2 terminals F and E for short to power supply or GND. 	Yes	Inspect the wiring harness and CAN system-related module. Repair or replace the malfunctioning part.
	• Is there any malfunction?	No	Replace the instrument cluster.
7		Yes	Go to the next step.
	 Turn the ignition switch off. Inspect the instrument cluster connector terminals for poor connection (such as damaged/pulled-out pins, and corrosion). Are the terminals normal? 	No	Repair or replace the terminal.

2007 ACCESSORIES & BODY, CAB Symptom Troubleshooting (Instrument Cluster) - MX-5 Miata

	1K 1I 1G 1E 1C 1A 1L 1J 1H 1F 1D 1B		
8	 Disconnect the negative battery cable. Measure the resistance between the instrument cluster connector terminals 1J and 1L. 	Yes	Inspect the wiring harness and CAN system-related module. Repair or replace the malfunctioning part.
	• Is the resistance 114-126 ohms?	No	Replace the instrument cluster.

NO. 8 TACHOMETER INDICATION IS DEFECTIVE

TACHOMETER INDICATION IS DEFECTIVE POSSIBLE CAUSE TABLE

8	Tachometer indication is defective
	PCM malfunction
	Instrument cluster malfunction
POSSIBLE CAUSE	Connector or pin malfunction
TOSSIBLE CAUSE	Short circuit in wiring harness between CAN-L, CAN-H and GND
	Open circuit in CAN wiring harness (CAN-L, CAN-H)
	CAN wiring harness (CAN-L, CAN-H) short each other

DIAGNOSTIC PROCEDURE

STEP	INSPECTION		ACTION
1	 Start the engine. Does the tachometer needle move smoothly? 	Yes	Troubleshooting completed.
	 Does the tachometer needle indicate correct engine speed? 	No	Go to the next step.
2			Go to the next step.
2	gauge, and the oil pressure gauge operate normally?	No	Go to Step 4.
3	• Start the instrument cluster input/output check		Inspect the PCM or connectors.
	mode.Inspect the tachometer using the check code 13.	No	Replace the instrument cluster.

2007 ACCESSORIES & BODY, CAB Symptom Troubleshooting (Instrument Cluster) - MX-5 Miata

	• Is the tachometer normal?		
4	Start the engine.	Yes	Inspect the PCM or connectors.
4	• Does the ABS warning light turn off?	No	Replace the instrument cluster.
_	 Disconnect the negative battery cable. Measure the resistance between the DLC-2 terminals F and E. 	Yes	Go to the next step.
5		No	Go to Step 7.
	• Is the resistance 54-66 ohms ?		
6	 Disconnect the negative battery cable. Inspect the DLC-2 terminals F and E for short to power supply or GND. 	Yes	Inspect the wiring harness and CAN system-related module. Repair or replace the malfunctioning part.
	• Is there any malfunction?	No	Replace the instrument cluster.
7	 Turn the ignition switch off. Inspect the instrument cluster connector terminals for poor connection (such as damaged/pulled-out pins, and corrosion). Are the terminals normal? 	Yes	Go to the next step.
,	1K 1I 1G 1E 1C 1A 1L 1J 1H 1F 1D 1B	No	Repair or replace the terminal.
8	 Disconnect the negative battery cable. Measure the resistance between the instrument cluster connector terminals 1J and 1L. 	Yes	Inspect the wiring harness and CAN system-related module. Repair or replace the malfunctioning part.
	• Is the resistance 114-126 ohms ?	No	Replace the instrument cluster.

NO. 9 WATER TEMPERATURE GAUGE INDICATION IS DEFECTIVE

WATER TEMPERATURE GAUGE INDICATION IS DEFECTIVE POSSIBLE CAUSE TABLE

9 Water temperature gauge indication is defective	
POSSIBLE CAUSE	 PCM malfunction Instrument cluster malfunction Connector or pin malfunction Short circuit in wiring harness between CAN-L, CAN-H and GND

2007 ACCESSORIES & BODY, CAB Symptom Troubleshooting (Instrument Cluster) - MX-5 Miata

- Open circuit in CAN wiring harness (CAN-L, CAN-H)
- CAN wiring harness (CAN-L, CAN-H) short each other

DIAGNOSTIC PROCEDURE

STEP	INSPECTION		ACTION	
1	• Start the engine.	Yes	Troubleshooting completed.	
1	 Does the water temperature gauge needle move to medium range gradually and stay there? 	No	Go to the next step.	
2	• Do the speedometer, the tachometer, and the oil		Go to the next step.	
	pressure gauge operate normally?	No	Go to Step 4.	
	 Start the instrument cluster input/output check mode. 	Yes	Inspect the PCM or connectors.	
3	Inspect the water temperature gauge using the check code 25.Is the water temperature gauge normal?	No	Replace the instrument cluster.	
	Start the engine.	Yes	Inspect the PCM or connectors.	
4	Does the ABS warning light turn off?	No	Replace the instrument cluster.	
5	 Disconnect the negative battery cable. Measure the resistance between the DLC-2 	Yes	Go to the next step.	
5	terminals F and E. • Is the resistance 54-66 ohms ?	No	Go to Step 7.	
6	 Disconnect the negative battery cable. Inspect the DLC-2 terminals F and E for short to power supply or GND. 	Yes	Inspect the wiring harness and CAN system-related module. Repair or replace the malfunctioning part.	
	• Is there any malfunction?	No	Replace the instrument cluster.	
7		Yes	Go to the next step.	
	 Turn the ignition switch off. Inspect the instrument cluster connector terminals for poor connection (such as damaged/pulled-out pins, and corrosion). Are the terminals normal? 	No	Repair or replace the terminal.	

2007 ACCESSORIES & BODY, CAB Symptom Troubleshooting (Instrument Cluster) - MX-5 Miata

	1K 11 1G 1E 1C 1A 1L 1J 1H 1F 1D 1B		
8	 Disconnect the negative battery cable. Measure the resistance between the instrument cluster connector terminals 1J and 1L. 		Inspect the wiring harness and CAN system-related module. Repair or replace the malfunctioning part.
	• Is the resistance 114-126 ohms ?	No	Replace the instrument cluster.

NO. 10 OIL PRESSURE GAUGE INDICATION IS DEFECTIVE (OIL PRESSURE GAUGE NEEDLE DOES NOT MOVE FROM THE L POSITION OR LESS)

OIL PRESSURE GAUGE INDICATION IS DEFECTIVE POSSIBLE CAUSE TABLE

	Oil pressure gauge indication is defective (oil pressure gauge needle does not move from the L position or less)
	PCM malfunction Instrument aluster malfunction
	Instrument cluster malfunction
POSSIBLE	Oil pressure switch malfunction
CAUSE	Connector or pin malfunction
0110.02	Short circuit in wiring harness between CAN-L, CAN-H and GND
	Open circuit in CAN wiring harness (CAN-L, CAN-H)
	CAN wiring harness (CAN-L, CAN-H) short each other

DIAGNOSTIC PROCEDURE

STEP	INSPECTION		ACTION
	• Start the engine.	Yes	Troubleshooting completed.
1	 Does the oil pressure gauge needle indicate L position or more? 	No	Go to the next step.
2	Bo the specdometer, the tachometer, and the	Yes	Go to the next step.
2		No	Go to Step 5.
3	• Does the engine oil need replenishment?	Yes	Add the engine oil.
		No	Go to the next step.

2007 ACCESSORIES & BODY, CAB Symptom Troubleshooting (Instrument Cluster) - MX-5 Miata

4	 Start the instrument cluster input/output check mode. Inspect the oil pressure gauge using the check 	Yes	Inspect the PCM, oil pressure switch, or connectors.
	code 28. • Is the oil pressure gauge normal?	No	Replace the instrument cluster.
_	Start the engine.	Yes	Inspect the PCM or connectors.
5	• Does the ABS warning light turn off?	No	Go to the next step.
6	 Disconnect the negative battery cable. Measure the resistance between the DLC-2 terminals F and E. Is the resistance 54-66 ohms? 	Yes	Go to the next step.
0		No	Go to Step 8.
7	 Disconnect the negative battery cable. Inspect the DLC-2 terminals F and E for short to power supply or GND. 	Yes	Inspect the wiring harness and CAN system-related module. Repair or replace the malfunctioning part.
	• Is there any malfunction?	No	Replace the instrument cluster.
8	 Turn the ignition switch off. Inspect the instrument cluster connector terminals for poor connection (such as damaged/pulled-out pins, and corrosion). Are the terminals normal? 	Yes	Go to the next step.
0		No	Repair or replace the terminal.
9	 Disconnect the negative battery cable. Measure the resistance between the instrument cluster connector terminals 1J and 1L. 	Yes	Inspect the wiring harness and CAN system-related module. Repair or replace the malfunctioning part.
	• Is the resistance 114-126 ohms ?	No	Replace the instrument cluster.