1990-93 ENGINE COOLING Drive Belt Routing & Adjustment - MX-5 Miata

#### 1990-93 ENGINE COOLING

#### **Drive Belt Routing & Adjustment - MX-5 Miata**

### **ADJUSTMENT**

NOTE: Ensure drive belts are not worn, cracked or frayed and are correctly mounted

on pulleys. See Fig. 1.

NOTE: If a new belt is used, adjust belt deflection at midpoint of new belt specification.






Fig. 1: Identifying Correct Belt Mounting Courtesy of MAZDA MOTORS CORP.

#### **ALTERNATOR**

Loosen alternator bolts and adjust belt deflection by turning adjusting bolt. See <u>Fig. 2</u>, <u>Fig. 6</u> and <u>Fig. 7</u>. See <u>ADJUSTMENT SPECIFICATIONS</u>. Tighten bolts to specification. See <u>TORQUE SPECIFICATIONS</u>.

1990-93 ENGINE COOLING Drive Belt Routing & Adjustment - MX-5 Miata




Fig. 2: Adjusting Alternator Belt Courtesy of MAZDA MOTORS CORP.

### A/C COMPRESSOR

Loosen locknut and adjust belt deflection by turning adjusting bolt. See  $\underline{Fig. 3}$ ,  $\underline{Fig. 6}$  and  $\underline{Fig. 7}$ . See  $\underline{ADJUSTMENT\ SPECIFICATIONS}$ . Tighten bolts to specification. See  $\underline{TORQUE\ SPECIFICATIONS}$ .

1990-93 ENGINE COOLING Drive Belt Routing & Adjustment - MX-5 Miata





Fig. 3: Adjusting A/C Compressor & Power Steering Pump Belt Courtesy of MAZDA MOTORS CORP.

1990-93 ENGINE COOLING Drive Belt Routing & Adjustment - MX-5 Miata



G00160472

Fig. 4: Adjusting A/C Compressor Belt Courtesy of MAZDA MOTORS CORP.

#### **POWER STEERING PUMP**

Loosen power steering pump bolt and nuts and adjust belt deflection by turning adjusting bolt. See <u>Fig. 3</u>, <u>Fig. 6</u> and <u>Fig. 7</u>. See <u>ADJUSTMENT SPECIFICATIONS</u>. Tighten bolts to specification. See <u>TORQUE</u> **SPECIFICATIONS**.

# **DRIVE BELT ROUTING**





Fig. 5: Identifying Drive Belt Routing & Deflection Check Point (1 Of 3) Courtesy of MAZDA MOTORS CORP.

1990-93 ENGINE COOLING Drive Belt Routing & Adjustment - MX-5 Miata

# P/S or P/S + A/C EQUIPPED



G00160468

Fig. 6: Identifying Drive Belt Routing & Deflection Check Point (2 Of 3) Courtesy of MAZDA MOTORS CORP.

1990-93 ENGINE COOLING Drive Belt Routing & Adjustment - MX-5 Miata

# A/C EQUIPPED




Fig. 7: Identifying Drive Belt Routing & Deflection Check Point (3 Of 3) **Courtesy of MAZDA MOTORS CORP.** 

# **ADJUSTMENT SPECIFICATIONS**

Check belt deflection when engine is cold, or has bin off for 30 minutes. NOTE:

#### **DEFLECTION SPECIFICATIONS**

Application	(1) Specification - In. (mm)
New Belt (2)	
Alternator	0.31-0.35 (8-9)
A/C Compressor	0.31-0.35 (8-9)
Power Steering Pump	0.31-0.35 (8-9)
Used Belt	
Alternator	0.35-0.39 (9-10)
A/C Compressor	0.35-0.39 (9-10)
Power Steering Pump	0.35-0.39 (9-10)
(1) Deflection with 22 lbs. (10 kg) pressure applied	midway on belt run.

Used on for less than 5 minutes.

1990-93 ENGINE COOLING Drive Belt Routing & Adjustment - MX-5 Miata

(2)

### **TENSION SPECIFICATIONS**

Application	(1) Specification - Lbs. (kg)
New Belt (2)	
Alternator	110-132 (50-60)
A/C Compressor	110-132 (50-60)
Power Steering Pump	110-132 (50-60)
Used Belt	
Alternator	95-110 (43-50)
A/C Compressor	95-110 (43-50)
Power Steering Pump	95-110 (43-50)
(1) Measure tension using Tension Gauge (49 9200 020), or equivalent.	
(2) Used on for less than 5 minutes.	

# **TORQUE SPECIFICATIONS**

## TORQUE SPECIFICATIONS

Application	Ft. Lbs. (N.m)
Alternator Adjusting Bolt	
"A"	14-18 (19-25)
"B"	27-38 (37-52)
A/C Compressor Locknut	27-38 (37-52)
Power Steering Pump Adjusting Bolt	
"A"	23-44 (31-46)
"B"	27-40 (37-54)
"C"	14-18 (19-25)