

PG009-02



Technical Service BULLETIN

January 18, 2002

Title: **REPLACEMENT VIN PLATES**

Models: All Models

TSB UPDATE NOTICE:

The information contained in this TSB updates PG007–01 dated May 4, 2001. Revised text is red and underlined. The changes will take place February 1, 2002.

Introduction Replacement VIN plates (metal plates riveted to dashboard) may be available from Toyota providing the request meets the criteria listed below.



NOTE:

All replacement plates for damaged and/or stolen vehicles are subject to approval by the Technical Compliance Department. If you have any specific questions, contact (310) 468-3390.

Wa Inform

| arranty mation | OP CODE | DESCRIPTION | TIME | OPN | T1 | T2 |
|-------------------|---------|----------------------------|------|-----|----|----|
| | N/A | Not Applicable to Warranty | - | _ | - | - |





APPLICATION FOR REPLACEMENT VIN PLATE



REASON FOR REPLACEMENT

□ ACCIDENT DAMAGE

REASON/EXPLANATION

PLEASE PROVIDE CORRECT VIN



| DEALER INFORMATION | | | | | |
|--------------------|------------------------------------|--|--|--|--|
| DEALER CODE: | | | | | |
| DEALER NAME: | | | | | |
| ADDRESS: | STREET ADDRESS | | | | |
| | CITY, STATE, ZIP CODE | | | | |
| TELEPHONE: | () AREA CODE, TELEPHONE NUMBER | | | | |
| CONTACT: | FIRST NAME, LAST NAME | | | | |

MAIL (*DO NOT FAX*) THE COMPLETED REQUEST FORM WITH THE OLD PLATE TO: TOYOTA MOTOR SALES, U.S.A. INC. TECHNICAL COMPLIANCE DEPARTMENT, S207 19001 S. WESTERN AVENUE TORRANCE, CA. 90509–2991